1. Install and Configure PCS Service for Plugins if not done.
2. Stop PCS Service if it is running.
3. Remove Existco.Plugins dll in the **Plugins** folder if existing.
4. Install Existco.Plugins by running the MSI Installer. It is defaulted to this location:
   ==C:\Program Files (x86)\Existco Pty Ltd\Plant Control System Service\Plugins\Existco.Plugins\==

5. The folder' structure in PCS Service should be like this