

Configuration Sheet
For
Zebra Motorola Symbol Zebra DS3578

1. Restore Defaults



***Restore Defaults**



Set Factory Defaults

2. USB OPOS



USB OPOS Handheld

3. No Headers or Terminators



Scan Options



*Data As Is

4. Disable Transmit Code ID Character



*None